





## Earth Solutions NW LLC

15365 NE 90<sup>th</sup> Street, Suite 100  
Redmond, WA 98052  
Main (425) 449-4704 | Fax (425) 449-4711  
www.esnw.com

## FIELD REPORT

Project No.	2953.11	Page	1 of 1	Report ID	2953.11 E 02032022
Date	Thu 2/3/2022	Weather	40°F, Raining		
Arrival/Departure Time(s)	12:00/12:45	Travel Time (hr)	1.5		
Project Name	Westridge Townhomes North Vertical				
Location	NE Discovery Dr & 9 <sup>th</sup> Ave NE, Issaquah				
ESNW Rep. & Phone	Adrien Leland				
Client Info/Contact	Polygon-WLH, LLC				
General Contractor Info/Contact					
Permit No(s).					
Reviewed By	LAC		SHA		
	Field Supervisor	Initials/Date	Project Manager	Initials/Date	
<small>Limitations: The presence of our field representative at the site is to provide our client with a source of professional advice, opinions, and recommendations based upon the field representative's observations and testing of the contractor's work. Our services do not include supervision or direction of the contractor, their employees, or agents. Geotechnical recommendations for obtaining project objectives may be made by our representatives; however, direction of the actual work should come from the owner or contractor, as appropriate. The contractor is responsible for complying with the contract documents at all times, regardless of the presence of our field representative. Jobsite safety, including compliance with all applicable state or federal regulations, is the sole responsibility of the contractor. The observations, recommendations, and conclusions provided in this field report are preliminary until reviewed by the ESNW project manager.</small>					

Footing or Caisson Subgrade	Conditions Observed
Building 16	Dense

As requested, ESNW rep was onsite to probe footing subgrade for building 16. While on site ESNW rep observed the following:

Upon arrival, ESNW rep observed that the contractor had brought building 16 to footing grade. ESNW rep probed the excavated footing subgrade using a 1/2" diameter steel T-probe. ESNW rep observed dense soil conditions in all probed areas. These observed conditions are considered suitable for the support of the proposed multifamily structures. Surficial mud and water should be removed prior to pouring.

ESNW rep will return when requested.